



PALM GROVE GOLF COMPLEX

135 CLAYTON STREET

BELLEVUE 6056

PHONE 9250 2222

FAX 9250 2222

ABN 35 542 843 034

Hydosmart International  
259 Fullarton Road  
Parkside  
SA 5063

2<sup>nd</sup> June 2006

Dear Paul,

Since using the Hydrosmart System at Palm Grove we have noticed a marked improvement in the colour and the quality of the grass.

Overall the course looks much greener and healthier although we have not used any extra fertilizers.

We have a salt content of 2,400 parts per million in our water and have had problems growing grass on some areas around the course. These areas are now growing well for the first time.

There has been a reduction in the blockage of sprinklers due to iron build up and our water usage is down by approximately 10% on previous summers.

We believe that the Hydrosmart System has been one of the better investments we have made for our Complex and have no hesitation in recommending it to any prospective customers.

Thank you for your continued interest, advise and support, it has been a pleasure to deal with you.

Yours sincerely,

David Currie