

Hydrosmart turf case study 2016: The grass on a Cricket Club's oval all starts dying from saline borewater, but once a new power supply is replaced the oval starts greening up inside 2 weeks;

Tony Plumridge:

"Hello, we at Barkers Creek Cricket Club purchased a Hydrosmart water conditioner a few years ago, and just realised that our outfield was looking very poor as the weather has got hotter. Our coach is a qualified electrician so he had a look at it and realised water has got into the power supply box and shorted out the panel, so I was wondering how much it was for a new power control box?"

Paul (Hydrosmart): (after supplying new power source)

"Hi Tony. Any feedback since it was repaired?"

Tony:

"Yeah, been nearly two weeks and it's starting to green up. It was nearly completely gone but it is showing good signs already"



Picture credit: Barker's Creek Cricket Club facebook page

www.facebook.com/barkerscreek.cricketclub